

TECH BULLETIN: SPITFIRE VALVE INSTALLATION ISSUES

Effective: 04/11/2024

Parts Affected: All assemblies, kits, or part orders containing Capstan Spitfire Valves

DETAILS

CapstanAg has been made aware of difficulty in installing SpitFire Valve assemblies, resulting in leaks. Valve assemblies for Arag/Hypro branded nozzle bodies, and Wilger nozzle bodies more than 10 years old, have been reported to be most prone to leaks after installation.

1. Improper Installation practices

- 1.1. Improper Installation can result in torn or twisted O-rings and will result in leaks.
 - 1.1.1. SpitFire coils **MUST NOT** be rotated upon installation. This will distort/damage the O-ring.
 - 1.1.2. Hold the coil firmly while only rotating the flynut to tighten the valve.



*O-RINGS DAMAGED FROM IMPROPER INSTALLATION
WILL APPEAR TORN OR DEFORMED*

- 1.2. More information on SpitFire valves can be found on the Capstan Ag resources page at <https://capstanag.com/resources/>
- 1.3. For specific part information and installation/maintenance procedures, refer to [Spitfire Valve Installation](#) on the resources page.
- 1.4. Videos demonstrating the correct installation of SpitFire valves can be found at <https://youtu.be/kwFzOziExEs> and by scanning this QR code.



2. Out-of-Round O-rings

2.1. O-rings that are misshapen or otherwise not fully round prior to installation are more likely to result in installation difficulties that may result in leaks.

✗ *NEEDS REPLACEMENT*



OUT-OF-ROUND

✓ *WORKING CONDITION*



ROUND AND CONNECTED

2.2. Inspect parts before installation to ensure the O-rings have arrived undamaged.

2.3. Capstan Ag will supply new O-rings at no cost to the customer to replace any out-of-round O-rings found prior to initial installation.