

Application Code Update

New PinPoint™ II Code Revisions

Effective: December 3, 2018

CapView: v 4.18
Power Hub: v 2.56
VCM: v 2.41

This version of code is only compatible with PinPoint™ II

BUG FIXES

- All nozzles will show the duty cycle jumping to 10% or 100% for one pulse and then return to the correct duty cycle.
- This issue is intermittent and it is likely that machines with the previous software release (Power Hub v 2.55) are or will exhibit the issue. CapstanAG recommends updating the software even if the machine is not exhibiting the issue.