

## Application Code Update

# PinPoint™ Code Revisions

Effective Date: Nov. 2, 2020

CapView: v 4.48  
Power Hub: v 2.84  
VCM: v 2.43

This version of code is only compatible with PinPoint™ II Systems

### FEATURES/ENHANCEMENTS

- Improved compass calibration: Procedure changes—add a 10 second wait time before moving
- Add an **Invalid GPS VTG** error message when a GPS is always showing a heading = 0.0
- Improved compass filters
- Improved boundary performance
- Changed the ISO filter to prevent the Viper error messages from crashing the Gateway hub

### BUG FIXES INCLUDED

- Fixed bugs in determining Gateway hub orientation
- Fixed cornering issues
- Fixed an error in generating bitmaps