

## Application Code Update

# PinPoint II™ Code Revisions

Effective Date: June 13, 2022

CapView: v 4.48  
Power Hub: v 2.92  
VCM: v 2.44

This version of code is only compatible with PinPoint II™ systems.

## Features/Enhancements

- This code includes compatibility for power hubs with new compass modules on serial numbers 1279 and later.
- This code is optional, yet backwards compatible, with older serial numbers prior to 1279.

## Software Update Notes:

Refer to Technical Bulletin TB22-06 for more information.

- If the system is properly functioning on CapView 4.48 and hub 2.87, update Gateway software, then complete a compass calibration.  
A factory reset is not necessary.
- For existing systems operating older revisions of CapView or Gateway software, physically install the hub, update CapView to 4.48, then set up the system. If the Capview code is updated, a factory reset should be done.