Application Code Update

PinPoint™ II Code Revisions

Effective Date: June 21, 2019

CapView: v 4.18
Power Hub: v 2.61*
VCM: v 2.41

This version of code is only compatible with PinPoint™ II Systems

* The Power Hub software is the only code that the changing for this code version. This revision is for all but only necessary if having compass calibration issues.

BUG FIXES INCLUDED

❏ Improved compass calibration