



# PinPoint™ II Software Features

\*\*\*Compatible software suites (CapView II, Power Hub, & VCM) are required for proper operation.

Software Details			Improvements	Corrections	Notes
Component	Version	Release Date			
CapView II	4.18	10/1/2018	<ul style="list-style-type: none"> <li>Ability to Save Nozzle and System Setup values independent of Location setup to make replacing components easier</li> <li>24-Series Valve compatibility without changing the boom configurations</li> <li>Up to 200 valve capability for larger booms or tighter nozzle spacing</li> </ul>	<ul style="list-style-type: none"> <li>Improved overlap control in narrow overlap areas</li> <li>Faster overlap processing times</li> <li>Gallon Counter now works correctly with recirculation systems</li> </ul>	<ul style="list-style-type: none"> <li>Not compatible with original PinPoint systems</li> </ul>
Power Hub	2.55	10/1/2018			
VCM	2.42	10/1/2018			
Component	Version	Release Date			
CapView II	4.11	10/16/2017	<ul style="list-style-type: none"> <li>Makes PinPoint II compatible with AGCO C-Series Sprayers</li> </ul>	<ul style="list-style-type: none"> <li>Fixes VCM errors to make compatible with AGCO C-Series Machines</li> </ul>	<ul style="list-style-type: none"> <li>Not compatible with original PinPoint systems</li> <li>Not a mandatory update for non-AGCO C-Series machines</li> </ul>
Power Hub	2.48	10/16/2017			
VCM	2.20	1/9/2018			
Component	Version	Release Date			
CapView II	4.11	10/16/2017	<ul style="list-style-type: none"> <li>Makes PinPoint II compatible with AGCO C-Series Sprayers</li> </ul>	<ul style="list-style-type: none"> <li>Corrects errors in the conversion to Metric Units</li> </ul>	<ul style="list-style-type: none"> <li>Not compatible with original PinPoint systems</li> </ul>
Power Hub	2.48	10/16/2017			
VCM	2.19	10/16/2017			



Software Details			Improvements	Corrections	Notes
<i>Component</i>	<i>Version</i>	<i>Release Date</i>	<ul style="list-style-type: none"> <li>• Individual Nozzle Boundary Control with CapMaps</li> <li>• Ability to Pulse at 31 Hz.</li> <li>• Allows up to 250 map uploads at once</li> <li>• Usable with all FAT formatted USB thumb drives</li> <li>• Spray with USB thumb drives in the back of the CapView II</li> <li>• No power-up delay required after Factory Reset</li> <li>• Faster processing time</li> <li>• Faster scroll bars</li> <li>• 15-Nozzle VCM Compatibility</li> <li>• Ability to set Pump Speed (RPM) Limit</li> <li>• Contact line with QRC code to Website</li> <li>• Expanded Portuguese Language</li> <li>• Advanced Menu Structure</li> <li>• Digital Copy of Manual and Software on USB thumb drives</li> </ul>	<ul style="list-style-type: none"> <li>• Fixes boom resetting preset issue, where a preset temporarily resets itself back on default when selected while in an open field until a different preset is selected followed by reselecting the desired preset</li> <li>• Fixes boundary file corruptions that appear in the CapView II as a .datat file, which generally refers to a missing file component in the original shapefile</li> </ul>	<ul style="list-style-type: none"> <li>• Not compatible with original PinPoint systems</li> </ul>
CapView II	4.05	5/15/2017			
Power Hub	2.44	11/30/2016			
VCM	2.16	11/30/2016			
<i>Component</i>	<i>Version</i>	<i>Release Date</i>			
CapView II	2.02	12/1/2017	<ul style="list-style-type: none"> <li>• Usable with all FAT formatted USB thumb drives</li> <li>• Spray with USB thumb drives in the back of the CapView II</li> <li>• No power-up delay required after Factory Reset</li> <li>• Ability to Pulse at 31 Hz</li> <li>• 15-Nozzle VCM Compatibility</li> <li>• Ability to set Pump Speed (RPM) Limit</li> <li>• Contact line with QRC code to Website</li> <li>• Advanced Menu Structure</li> </ul>		
Power Hub	2.44	11/30/2016			
VCM	2.16	11/30/2016			