

Application Code Update

PinPoint™ Code Revisions

Effective Date: May 24, 2021

CapView: v 4.48
Power Hub: v 2.87
VCM: v 2.44

This version of code is only recommended with PinPoint™ II systems with an RCM.

BUG FIXES INCLUDED

- ❑ Corrects issues high duty cycles in VCM software version 2.43.

NOTE: The high duty cycle issues have only been found in VCM software version 2.43. Other previous software versions do not present the same error. This software update is only needed for VCM software version 2.43.