

## Bootloader and Application Code Update

# SelectShot™ Code Revisions

Effective Date: December 3, 2021

VT Bootloader:	3.22.000
VT Application:	3.22.000
IO Bootloader:	3.22.000
IO Application:	3.22.000

### FEATURES/ENHANCEMENTS

- Pump Control improved in Auto Mode
- VT and IO software files now include the revision number in the file name.
- Max Seed Frequency added to prevent circuit board damage
- Min Valve Duty Cycle added to prevent low-rate erratic behavior
- Virtual Terminal (VT) operator interface aesthetic and functional Improvements

### BUG FIXES INCLUDED

- Diagnostics page units of measure conversion fixed
- Disabling and enabling rows functionality fixed
- Hilldrop seeding application improvements
- Tip Calibration VT and catch test bug fixes
- Valve Diagnostics improvements