
PinPoint III Envelop Software Update

5/25/2022

Gateway Hub Revision 1.02.24

Features:

- Equipment Technologies Apache remote fill station
 - Enable remote fill station pump switch
 - Preset PWM value added to enable chemical educator
- Fill Flowmeter Support
 - Equipment Technologies Apache fill flowmeter support added
 - Miller Sprayer fill flowmeter support added
 - Fill flowmeter resets to 0 when master is switch on and boom flow is detected
- Fence Row Nozzles
 - Option added for task control fence row nozzles when using virtual switches (on screen)
 - Option added for external switch box control of fence row nozzles
- Gallon counters use double precision variables
- Click anywhere on screen to exit pop-up menu
- Conventional Rate Control through Gateway Hub
 - No solenoid valves Required

Bug Fixes

- Synchronized gallon count up and tank count down
- Resolved bug causing recirculation icon to randomly disappear
- Resolved bug causing overcount of gallons when gallon counter was above 17,000 gallons
- Resolved application rate issue when specific gravity was not equal to 1.0
- Resolved offset boom issue when operating one fence row nozzle attached to a VCM
- Resolved bug that required exiting the softboom assignment screen with only the double back arrows

