

## Tech Bulletin: PinPoint III Apache Remote Fill Monitor Inoperative

Units Affected: PPIII Systems Installed on Equipment Technologies Apache Sprayers.

### ISSUE

The remote fill station monitor does not work correctly. The monitor will not track gallons correctly or will read only "- - - -". Only resetting battery power to the PinPoint III system after the machine is up and running will allow correct operation until the issue is resolved.

### RESOLUTION

The function instance in the machine fill station monitor must be set to 1.

1. Press the **NEXT** or **PREVIOUS** soft key on the fill station monitor until the **Monitor Information** page is displayed.
2. Press the **INST** soft key to change the **INSTANCE** value from 0 to 1.
3. Cycle ignition power

